



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah


DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program May 14, 2013

Reviewed: 

Mine Name: Snow White 1 Mine	Permit Number: M/049/0030
Operator Name: Interstate Brick Company	Inspection Date: May 14, 2013
Inspector(s): Lynn Kunzler & April Abate	Time: 2:00 PM
Other Participants: Tom Nicolaysen (Intern)	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Permit Fees: Paid \$500 2/4/2013

Bond Amount: Surety 143,300

Purpose of Inspection:

The purpose of the inspection is to introduce new lead, April Abate to the site.


Inspection Summary:

Photos were taken to document site conditions.

Mining activity was observed during the time of inspection at the south pit. Roger Peck, of Peck Construction was operating the excavator at the mine. Lynn had some question about the size of the disturbance on the south side of the permit area. This area bordered an ephemeral drainage and it appeared to Lynn that they were outside of their permitted boundary. After checking mine maps in the NOI, it was decided that they were not outside their permitted boundary. Additionally, Mr. Peck indicated that the area was to be partially reclaimed over the next week.

Conclusions and Recommendations:

None at this time. Try to revisit the site to check status of reclamation of south pit area.

Inspector's Signature 

cc: Interstate Brick Operator
BLM

O:\M049-Utah\M0490030-SnowWhite\inspections\Insp_051413.doc





View of head wall and the road to the mine from the north end of the site.



Looking north along the headwall; disturbed areas.



Current activity at the site.



Disturbance at the southwest corner of the site which will be partially reclaimed in a week.



Figure 1 Aerial Photo